

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Sacramento Maintenance Yard Putah Creek

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sacramento Maintenance Yard Putah Creek

Waterway				Bank	Unit Miles
Unit No. 01 Putah Creek or North Levee				Left	8.99
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	4/6/2010 - 4/6/2010				
DWR Inspector	Herman Phillips				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Putah Creek or North Levee						Left	8.99	04/06/2010 04/06/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.03	5.97	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.523277 ° -121.631438 °	38.518472 ° -121.732990 °	1 Y
2	0.03	0.28	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.523238 ° -121.631447 °	38.520208 ° -121.633342 °	6
3	0.27	0.34	Earthen Levee	Encroachments	LS	PO	Landscaping	38.520305 ° -121.633168 °	38.520000 ° -121.634358 °	2
4	0.29	0.29	Earthen Levee	Encroachments	LS	PO	Buildings	38.520177 ° -121.633528 °	38.520177 ° -121.633530 °	3
5	0.30	5.97	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.520052 ° -121.633775 °	38.518473 ° -121.732988 °	7
6	1.23	1.23	Earthen Levee	Encroachments	LS	M	Equipment	38.516752 ° -121.649758 °	38.516752 ° -121.649758 °	4
7	1.55	2.72	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.515288 ° -121.655077 °	38.517438 ° -121.676068 °	13 Y
8	2.11	2.17	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	38.515798 ° -121.666497 °	38.515863 ° -121.667445 °	9
9	2.18	2.22	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	38.515800 ° -121.666500 °	38.515860 ° -121.667345 °	8
10	5.79	5.89	Earthen Levee	Encroachments	WS	PO	Crops	38.518305 ° -121.729815 °	38.518420 ° -121.731763 °	15
11	6.76	6.93	Earthen Levee	Encroachments	LS	PO	Fences	38.517635 ° -121.747220 °	38.517675 ° -121.750247 °	5
12	6.97	6.98	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.517700 ° -121.750883 °	38.517697 ° -121.751055 °	10
13	7.00	7.01	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.517690 ° -121.751562 °	38.517652 ° -121.751730 °	12
14	7.02	7.03	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.517578 ° -121.751815 °	38.517583 ° -121.752180 °	14
15	7.03	7.07	Earthen Levee	Encroachments	LS	PO	Fences	38.517565 ° -121.751940 °	38.517600 ° -121.752697 °	17
16	8.25	8.50	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.519643 ° -121.773245 °	38.521665 ° -121.777075 °	18
17	8.26	8.50	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.519650 ° -121.773262 °	38.521665 ° -121.777073 °	11
18	8.50	8.82	Earthen Levee	Encroachments	LS	PO	Fences	38.521580 ° -121.777172 °	38.523932 ° -121.782100 °	20

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Putah Creek or North Levee	Left	8.99	04/06/2010 04/06/2010	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.03
End Levee Mile	5.97
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Looking downstream on land side unit 1 Putah Creek. District will have this mowed later in the spring.

phillips_s_20100707_158.jpg



Levee Mile Report Line	1
Start Levee Mile	0.03
End Levee Mile	5.97
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Looking downstream on water side levee mile 0.024 Typical view of Unit 1 before mowing.

phillips_s_20100707_159.jpg



Levee Mile Report Line	7
Start Levee Mile	1.55
End Levee Mile	2.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments

This ditch is located within the 10-foot easement and has been at this location for several years.

phillips_s_20100316_024.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Putah Creek or North Levee	Left	8.99	04/06/2010 04/06/2010	Herman Phillips

Levee Mile Report Line	7
Start Levee Mile	1.55
End Levee Mile	2.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Another view of ditch looking downstream landward.

phillips_s_20100316_025.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sacramento Maintenance Yard Putah Creek

Waterway				Bank	Unit Miles
Unit No. 02 Putah Creek or South Levee				Right	7.30
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	4/29/2010 - 4/29/2010				
DWR Inspector	Herman Phillips				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Putah Creek or South Levee						Right	7.30	04/29/2010 04/29/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.28	Earthen Levee	Encroachments	WS	C	Agricultural Ditch	38.504930 ° -121.663150 °	38.508830 ° -121.663280 °	24
2	0.17	0.31	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.507113 ° -121.662687 °	38.508968 ° -121.663432 °	3
3	0.20	0.30	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	38.507410 ° -121.662727 °	38.508775 ° -121.663228 °	26
4	0.21	0.30	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	38.507598 ° -121.662815 °	38.508835 ° -121.663212 °	1
5	1.09	1.10	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: This location erosion site has been partially repaired by the land owner however there is some controversial issues here between the Maintenance yard and owner as to who is responsible for repairs. PICTURES and a report has been taken on this site.	38.511645 ° -121.676747 °	38.511612 ° -121.676770 °	27 Y
6	2.10	2.13	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.515348 ° -121.694042 °	38.515398 ° -121.694590 °	22
7	2.10	2.13	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.515350 ° -121.694110 °	38.515385 ° -121.694558 °	23
8	5.69	5.69	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.515557 ° -121.757165 °	38.515557 ° -121.757165 °	10 Y
9	6.42	6.42	Earthen Levee	Erosion / Bank Caving	LS	M	Note and monitor erosion site.	38.517417 ° -121.769950 °	38.517417 ° -121.769953 °	28
10	6.59	6.65	Earthen Levee	Encroachments	WS	PO	Crops	38.518088 ° -121.772947 °	38.518353 ° -121.773935 °	6
11	6.64	6.66	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.518270 ° -121.773698 °	38.518357 ° -121.773960 °	29
12	6.70	6.72	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.518622 ° -121.774525 °	38.518730 ° -121.774767 °	30
13	6.76	6.82	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.519022 ° -121.775298 °	38.519585 ° -121.776285 °	31
14	7.03	7.04	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	38.521298 ° -121.779452 °	38.521327 ° -121.779505 °	2
15	7.05	7.07	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	38.521433 ° -121.779715 °	38.521605 ° -121.780055 °	4
16	7.16	7.16	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.522242 ° -121.781460 °	38.522242 ° -121.781463 °	32

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Putah Creek or South Levee						Right	7.30	04/29/2010 04/29/2010	Herman Phillips

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
17	7.17	7.18	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	38.522327 ° -121.781477 °	38.522408 ° -121.781638 °	5
18	7.24	7.30	Earthen Levee	Encroachments	WS	PO	Crops	38.522752 ° -121.782912 °	38.522685 ° -121.784757 °	13

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Putah Creek or South Levee	Right	7.30	04/29/2010 04/29/2010	Herman Phillips

Levee Mile Report Line	5
Start Levee Mile	1.09
End Levee Mile	1.10
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving

Photo shows partial repair of slope damage.

phillips_s_20100316_026.jpg



Levee Mile Report Line	5
Start Levee Mile	1.09
End Levee Mile	1.10
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving

slope damage some repairs made. Proper repair need to be done at this site with compaction test to verify compaction.

phillips_s_20100316_027.jpg



Levee Mile Report Line	5
Start Levee Mile	1.09
End Levee Mile	1.10
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving

Another view standing on toe of slope looking upstream.

phillips_s_20100316_028.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sacramento Maintenance Yard Putah Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Putah Creek or South Levee	Right	7.30	04/29/2010 04/29/2010	Herman Phillips

Levee Mile Report Line	8
Start Levee Mile	5.69
End Levee Mile	5.69
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking upstream from old Davis road unit 2.

phillips_s_20100707_157.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected